

Governor

DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

0053

Dee C. Hansen Executive Director Nielson, Ph.D.
Division Director Dianne R. Nielson, Ph.D.

355 West North Temple 3 Triad Center, Suite 350

Salt Lake City, Utah 84180-1203

801-538-5340

Partial: XX Complete: ___Exploration_ Inspection Date/Time: December 23, 1992/10:00am-12:00pm

INSPECTION REPORT

Date of Last Inspection: November 28, 1992

Min	e Name: Skyline Mine County: Carbon	Permit Number: ACT/007/005									
Permittee and/or Operator's Name: Coastal States Energy/Utah Fuel											
Business Address: P. O. Box 719, Helper, UT 84527											
T	e of Mining Activity: Underground XX Surf	face Prep Plant Other									
1 yp	e of mining activity: underground AA Suff	.ace riep. rianc other									
Officials(s): State: Stephen J. Demczak Company: Keith Zobell											
Federal Official(s): Weather Conditions: Cool w/2' snow											
Existing Acres:Permitted-7067.11 Disturbed-62.08 Regraded-Seeded-Bonded-62.41											
Increased/Decreased: PermittedDisturbedRegradedSeededBonded											
Sta	tus:Exploration/_X_Active/Inactive/_	Temp Cessation/Bond Forfeiture									
R	eclamation (Phase I/Phase II/Final B	Sond Release/LiabilityYear)									
	REVIEW OF PERMIT, PERFORMANCE STANDARDS & PE	ERMIT CONDITION REQUIREMENTS									
Insti	ructions										
1.	Substantiate the elements on this inspection by checking the	appropriate performance standard.									
i	a. For complete inspections provide narrative justification for any elements not fully inspected unless										
	element is not appropriate to the site, in which case ch										
1	 For partial inspections check only the elements evaluate 	ed.									
	Document any noncompliance situation by referencing the NOV	/ issued at the appropriate performance standar									
	listed below.										
3.	Reference any narratives written in conjunction with this in	spection at the appropriate performance standar									
	listed below.										
	Provide a brief status report for all pending enforcement a	actions, permit conditions, Division Orders, an									
i	amendments.										
		ALUATED N/A COMMENTS NOV/ENF									
	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE										
	SIGNS AND MARKERS										
	TOPSOIL										
	HYDROLOGIC BALANCE:										
a.		[] [] [XX] [] [XXI [] [XXI [] [] [] [] [] [] [] [] [] [
b.		$\frac{(XX)}{(XX)}$ $\frac{(XX)}{(XX)}$ $\frac{(XX)}{(XX)}$									
c.	OTHER SEDIMENT CONTROL MEASURES WATER MONITORING										
_e.											
	EXPLOSIVES										
	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES										
	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	$\begin{array}{c ccccc} \hline C & \hline C &$									
	NONCOAL WASTE	[XY] $[XY]$ $[XY]$ $[XY]$									
9.	PROTECTION OF FISH, WILDLIFE AND	<u>[] [] [] </u>									
10	RELATED ENVIRONMENTAL VALUES SLIDES AND OTHER DAMAGE										
10. 11.	CONTEMPORANEOUS RECLAMATION										
12.	BACKFILLING AND GRADING										
13.	REVEGETATION										
14.	SUBSIDENCE CONTROL										
15.	CESSATION OF OPERATIONS										
16.	ROADS:										
a.	CONSTRUCTION/MAINTENANCE/SURFACING										
b.	DRAINAGE CONTROLS	<u>[] [XX] [] [XX]</u>									
17.	OTHER TRANSPORTATION FACILITIES										
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS										
	AVS CHECK (4th Quarter-April, May, June)										
20.	AIR QUALITY PERMIT										
21.	BONDING & INSURANCE										

INSPECTION REPORT (Continuation sheet)

Page <u>2</u> of <u>2</u>

PERMIT NUMBER: ACT/007/005 DATE OF INSPECTION: December 23, 1992

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permit -

Skyline presently has two outstanding Division Orders: 92C (Response to Division Order 92A and 92D) and 92E (Waste Rock Ditch Design). They also have two amendments: 92K (Renewal Response) and 92M (Drainage at loadout).

4b. Sediment Ponds and Impoundments -

The sediment pond at mine site and loadout did contain water at he time of inspection. Only the mine site pond was discharging but there were no water samples taken. Water samples will be taken on the next complete inspection. The loadout pond was functioning as designed and all slopes (embankments) were snow covered.

8. Noncoal Waste -

Throughout the mine yards, pallets were left after being unloaded and they should either be placed and/or stacked somewhere for potential use or disposed of in a non-coal waste container.

16. Roads: Drainage Controls -

The ditch to the mine site stockpile should be regraded and to eliminate tire tracks within the ditch. All drainage was still utilizing the ditch and functioning correctly.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:

Mailed	i to:	Coast	al Stat	es Ene	rgy/Utah	Fuel,	Keith	Zobell	
Mailed	i to:	Bern	ie Fre	eman (O	SM)				
Given	to:	Joe H	lelfric	n (DOGM)				
Filed	to:	Price	Field	Office					
Date:	Janua	ary 5,	1993		_				

Inspector's Signature and Number:

Stephen J. Demczak

#39